
QST JAN 11 WATTMETER TWO A TO D CONVERTER BD REQUIRED A TO D CONVERTER BD A TO D CONVERTER BD G 0 Τ • C 1 FROM A TO D 1 14 • ۲ GND C2 C2 C20 2 C24 R8 Ř Ø 0 **U**5 •••• • GN 1 Ш ັ R4 ٩ MTR S Σ

new 2.5 volt ref circuits

NOTE: U7, C20, C24, AND C25 ARE MOUNTED ON THE BOTTOM OF THE BOARD



NOTE: THE SCHEMATIC IN QST SHOWS TWO R1 RESISTORS, AND NO R2 ONE OF THESE R1'S IS R2

THE PARTS LIST, R1 AND R2 AND THE SAME VALUE